

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 03 2015

BRADENHEAD TEST REPORT

RECEIVED

Operator Name RESOLUTE NATURAL RESOURCES	API Number 3002505177
Property Name BC DICKINSON D	Well No. 3

Surface Location

UL - Lot E	Section 35	Township 14S	Range 39E	Feet from 1980	N/S Line N	Feet From 660	E/W Line W	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL ☒ YES	NO	SHUT-IN YES	NO	INJECTOR INJ	SWD	PRODUCER OIL	GAS	DATE
--	----	----------------	----	-----------------	-----	-----------------	-----	------

OBSERVED DATA

	(A) Surface	(B) Interim (1)	(C) Interim (2)	(D) Prod. Chng	(E) Tubing
Pressure	0	0		0	
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☐
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid Injected for Waterflood if applicable
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

TA STATUS EXTENSION

Signature: M. Dickinson	OIL CONSERVATION DIVISION
Printed name: MURE DICKSON	Entered into RBDMS
Title: OPERATIONS SUPERVISOR	Re-test
E-mail Address:	
Date: 7/29/15	Phone: 432-661-1600
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

AUG 06 2015