

HOBBS OCD

JUL 14 2015

RECEIVED

District 1
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name <i>Apache Corp</i>	API Number <i>30-025-09884</i>
Property Name <i>11MGSAL</i>	Well No. <i>609</i>

Surface Location

UT Lot <i>1</i>	Section <i>20</i>	Township <i>19S</i>	Range <i>37E</i>	Feet from <i>1980</i>	N/S Line <i>S</i>	Feet from <i>660</i>	E/W Line <i>E</i>	County <i>Lea</i>
--------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR <i>INJ</i>	SWD	PRODUCER OIL	GAS	DATE <i>7-14-15</i>
------------------	----	----------------	----	------------------------	-----	-----------------	-----	------------------------

OBSERVED DATA

	(A) Surface	(B) Intern(1)	(C) Intern(2)	(D) Prod Csg	(E) Tubing
Pressure				<i>630</i>	<i>0</i>
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(D) Bleeds down to a trickle but builds back up with no pressure on the tubing. The well is shut-in

Failed

BS 8/7/2015

Signature: <i>J. Ellison</i>	OIL CONSERVATION DIVISION
Printed name: <i>Jim Ellison</i>	Entered into RBDMS
Title: <i>Instrument Tech</i>	Rc-test
E-mail Address: <i>J.D. Ellison @ apache corp. com</i>	
Date:	
Phone: <i>575-441-7734</i>	
Witness:	

AUG 14 2015