

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 13 2015

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron	API Number 3002538641
Property Name Central Vacuum Unit	Well No. 459

Surface Location									
1/4 - Lot	Section 31	Township 17S	Range 35E	Feet from	N/S Line	East Front	E/W Line	County LEA	

Well Status									
TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR INJ	SWD	OIL	PRODUCER GAS	DATE 6-25-2015	

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	N/A	N/A	0	1000
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 X
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR X
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 8/7/2015

Signature: Tanne Dettan	OIL CONSERVATION DIVISION
Printed name: Tanne Dettan Chevron	Entered into RBDMS
Title: FSI	Re-test
E-mail Address: TZM@chevron.com	
Date: 6/25/2015	Phone: 575-444-4498
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

AUG 14 2015