

HOBBS OCD

AUG 17 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON	API Number 30 025 30967
Property Name VGWU	Well No. 49

A Surface Location

Loc. Lat M	Section 30	Township 17N	Range R35E	Feet from 990	N/S Line S	Feet from 895	E/W Line W	County LEA
----------------------	----------------------	------------------------	----------------------	-------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

YES ☒ NO ☐	YES ☒ NO ☐	YES ☐ NO ☐	YES ☐ NO ☐	YES ☐ NO ☐	YES ☐ NO ☐	YES ☐ NO ☐	YES ☐ NO ☐	YES ☐ NO ☐	DATE 8/4/2015
---	---	--	--	--	--	--	--	--	-------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod C.sug	(E)Tubing
Pressure	ϕ	ϕ	N/A	ϕ	ϕ
Flow Characteristics					
Pull	Y/N ☒	Y/N ☒	Y/N ☒	Y/N ☒	CO2 ☐
Steady Flow	Y/N ☒	Y/N ☒	Y/N ☒	Y/N ☒	WTR ☐
Surges	Y/N ☒	Y/N ☒	Y/N ☒	Y/N ☒	GAS ☐
Down to nothing	Y/N ☒	Y/N ☒	Y/N ☒	Y/N ☒	Type of Fluid
Gas or Oil	Y/N ☒	Y/N ☒	Y/N ☒	Y/N ☒	Injected for
Water	Y/N ☒	Y/N ☒	Y/N ☒	Y/N ☒	Water flood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Eddie Gallager	OIL CONSERVATION DIVISION
Printed name: Eddie Gallager	Entered into RBDMS
Title: SUP	Re-test
E-mail Address: e.gallager@chevron.com	
Date: 8/4/15	Phone: 575-631-8516
Witness: [Signature]	

INSTRUCTIONS ON BACK OF THIS FORM

AUG 20 2015