

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 14 2015

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Apache Oil Corp.	API Number 30-025-06532
Property Name NEDU	Well No. 511

Surface Location

UL - Lot M	Section 11	Township 21S	Range 37E	Feet from 660	N/S Line S	Feet From 660	E/W Line W	County Lea
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR ☒ INJ	SWD	OIL PRODUCER OIL ☒ GAS	DATE 5-3-15
--	--	--	-----	--	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	$\emptyset$	$\emptyset$	N/A	20	1150
Flow Characteristics					
Puff	Y / ☒ N	Y / ☒ N	Y / N	☒ Y / N	CO2 ☐
Steady Flow	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	WTR ☒
Surges	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	GAS ☐
Down to nothing	Y / ☒ N	Y / ☒ N	Y / N	☒ Y / N	Type of Fluid
Gas or Oil	Y / ☒ N	Y / ☒ N	Y / N	☒ Y / N	Injected for
Water	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Prod. Csgs. Blowdown 10 secs.

Signature: Tracy Cole	OIL CONSERVATION DIVISION
Printed name: Tracy Cole	Entered into RBDMS ☒
Title: Pumper	Re-test
E-mail Address: tracy.cole@apachecorp.com	
Date: 5-3-15	Phone: 575-441-5196
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

AUG 28 2015