

JUL 14 2015

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache Oil Corp.	* API Number 30-025-016572
Property Name NEDU	Well No. 813

7. Surface Location

UL - Lot F	Section 23	Township 21S	Range 37E	Feet from 1980	N/S Line N	Feet From 1980	E/W Line W	County Lea
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR ☒ IN ☐ SWD	PRODUCER OIL ☐ GAS	DATE 3-22-15
--	--	---	---	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	$\emptyset$	$\emptyset$		500	1175
Flow Characteristics					
Puff	Y/ ☒ N	Y/ ☒ N	Y/N	☒ Y/ ☐ N	CO2 ☐
Steady Flow	Y/ ☒ N	Y/ ☒ N	Y/N	Y/ ☒ N	WTR ☐
Surges	Y/ ☒ N	Y/ ☒ N	Y/N	Y/ ☒ N	GAS ☐
Down to nothing	Y/ ☒ N	Y/ ☒ N	Y/N	☒ Y/ ☐ N	Type of Fluid
Gas or Oil	Y/ ☒ N	Y/ ☒ N	Y/N	Y/ ☒ N	Injected for
Water	Y/ ☒ N	Y/ ☒ N	Y/N	☒ Y/ ☐ N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Prod Casing - Water blow down less than a min.

Signature: <i>Tracy Cole</i>	OIL CONSERVATION DIVISION
Printed name: Tracy Cole	Entered into RBDMS <i>[initials]</i>
Title: Pumper	Re-test
E-mail Address: tracy.cole@apache.corp.com	
Date: 3-22-15	Phone: 575-441-5196
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

AUG 28 2015