

AUG 13 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name <i>Chevron USA Inc</i>	API Number <i>30 025 13238</i>
Property Name <i>Dollarhide West Dollarhide Drinkard</i>	Well No. <i>WDDU 25</i>

Surface Location

UL - Lot <i>5</i>	Section <i>29</i>	Township <i>24S</i>	Range <i>30E</i>	Feet from <i>1980</i>	N/S Line <i>S</i>	Feet From <i>1980</i>	E/W Line <i>E</i>	County <i>LEA</i>
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA/B WELL YES ☒ NO ☐	SHUT-IN YES ☐ NO ☒	INJECTOR ☒ INJ ☐ SWD	PRODUCER OIL ☐ GAS ☐	DATE <i>7/28/2015</i>
--	--	--	---	--------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0	0	15 psi	1320 psi
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☒
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Austin Stringfellow</i>	OIL CONSERVATION DIVISION
Printed name: <i>Austin Stringfellow</i>	Entered into RBDMS
Title: <i>Field specialist</i>	Re-test
E-mail Address: <i>ETVI@chevron.com</i>	
Date: <i>7/28/2015</i>	Phone: <i>432-215-8802</i>
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

AUG 31 2015