

AUG 07 2015

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON USA Inc	API Number 3002524314-
Property Name VG SAU	Well No. 31

Surface Location

1/4 - Lot 5	Section 2	Township T18S	Range R34E	Feet from 2630	N/S Line S	Feet From 1330	E/W Line E	County Lea
-----------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR YES ☒ NO	SWD	OIL	PRODUCER GAS	DATE 7/22/2015
--	--	---	-----	-----	-----------------	--------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csing	(E)Tubing
Pressure	0	N/A	N/A	0	2200
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☒
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Eddie Galt	138 8/28/2015
Printed name: EDDIE GALT	OIL CONSERVATION DIVISION
Title: SSLS	Entered into RBDMS
E-mail Address: e.galt@chevron.com	Re-test
Date: 7/22/15	Phone: 575-601-8516
Witness: [Signature]	

INSTRUCTIONS ON BACK OF THIS FORM