

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

BRADENHEAD TEST REPORT

RECEIVED	Operator Name	API Number
	Property Name	Well No.

AUG 07 2015

Cherxon

30 025 31699

VCHW

38

Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
M	25	T19S	R34E	1217	S	24	W	Lea

Well Status

YES	TA'D WELL	YES	SHUT-IN	INJ	SWD	OIL	PRODUCER	GAS	DATE
	NO		NO						7/17/2015

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod C'sng	(E)Tubing
Pressure	Ø	N/A	N/A	Ø	1450
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR X
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid injected for waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Eddie Galleaga</i>	B8 8/28/2015
Printed name: EDDIE GALLEAGA	OIL CONSERVATION DIVISION
Title: SSPS	Entered into RBDMS
E-mail Address: eiv@Cherxon.com	Re-test
Date: 7/17/15	
Phone: 575-631-8516	
Witness: <i>John Soren</i>	

INSTRUCTIONS ON BACK OF THIS FORM

AUG 31 2015