

HOBBS OCD

AUG 07 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

RECEIVED	Operator Name	API Number
	Property Name	Well No.
	Chevron USA Inc	30025 31835
	VGLW	9

Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
C	25	TNS	R34E	73	N	1411	W	Lea

Well Status

TA'D WELL	YES	NO	SHUT-IN	YES	NO	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE
											7/16/2015

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	Ø	N/A	N/A	Ø	280
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR X
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Ø/N	Y/N	Y/N	Ø/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Eddy Gallegos</i>	OIL CONSERVATION DIVISION
Printed name: EDDY GALLEGOS	
Title: SSPS	
E-mail Address: eiv@chevron.com	
Date: 7/16/15	
Phone: 575-631-8516	Entered into RBDMS
Witness: <i>[Signature]</i>	Re-test

INSTRUCTIONS ON BACK OF THIS FORM

AUG 31 2015