

HOBBS OCU

AUG 07 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

RECEIVED	Operator Name	API Number
	USA INC	30 025 31828
Property Name		Well No:
VAGU		41

Surface Location									
UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County
5	25	T19S	R34E		1377	S	1646	E	Lea

Well Status									
TA'D WELL	YES	NO	YES	SHUT-IN	NO	INJ	SWD	PRODUCER	GAS
									DATE
									7/17/2015

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	Ø	N/A	N/A	Ø	Ø
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	Y / N	CO2 —
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR X
Surges	Y / N	Y / N	Y / N	Y / N	GAS —
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>[Signature]</i>	8/28/2015
Printed name: EDDIE GALLER	OIL CONSERVATION DIVISION
Title: SSPS	Entered into RBDMS
E-mail Address: e.v.g@chevron.com	Re-test
Date: 7/17/15	
Phone: 575-631-8516	
Witness: <i>[Signature]</i>	

INSTRUCTIONS ON BACK OF THIS FORM

AUG 31 2015