

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 07 2015

RECEIVED

BRADENHEAD TEST REPORT

Operator Name ✓ Chevron USA Inc						API Number 30-025-31839			
Property Name ✓ Vacuum Gloria West						Well No. 68			
1. Surface Location									
UL - Lot ✓ H	Section 36	Township 17S	Range 34E	Feet from 1728	N/S Line N	Feet From 351	E/W Line E	County Lea	
Well-Status									
TA'D WELL YES		SHUT-IN NO		INJECTOR NO		PRODUCER YES		DATE 7/21/15	

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	0	1050
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ✓
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Water flood if
					applies.

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: ✓ [Signature]		OIL CONSERVATION DIVISION	
Printed name: EDYNE GARCIA		Entered into RBDMS	
Title: SSPS		Re-test	
E-mail Address: edynegarcia@chevron.com			
Date: 7/21/15	Phone: 575-631-8516		
Witness: [Signature]			

INSTRUCTIONS ON BACK OF THIS FORM

AUG 31 2015