

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 20 2015

BRADENHEAD TEST REPORT

RECEIVED

Operator name: 1/4-164 2D
Property name: CHRISTMAS 28 #1
710 75 78 0000
#1

7. Surface Location

UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County
E	28	22S	37E		1650	N	330	W	Lea


Well Status

YES	TA'D WELL	YES	SHUT-IN	INJ	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE
	NO		NO							8/11/15

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure				90	100
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	BB 8/29/2015
Printed name: RUSSELL HARSTLOFF	OIL CONSERVATION DIVISION
Title: FORMAN	Entered into RBDMS
E-mail Address:	Re-test
Date:	
Phone:	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

SEP 01 2015