

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 07 2015

RECEIVED

BRADENHEAD TEST REPORT

Operator Name ✓ Chevron	API Number 3002502953
Property Name Central Vacuum Unit	Well No. 64

Surface Location

UL - Lot F	Section 31	Township N1S	Range 35 E	Feet from 1980	N/S Line N	Feet From 1980	E/W Line W	County Lea
----------------------	----------------------	------------------------	----------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status


TA'D WELL YES	NO	YES	SHUT-IN NO	INJ	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE 7/16/15
-------------------------	-----------	-----	----------------------	-----	----------	-----	------------	----------	-----	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	15	45		350	450
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ☒
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	gas Y / N	gas Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Both Surface & Intermediate Blew down to Ops
in 10 seconds

Signature: 	BS 8/30/2015
Printed name: Daniel Pace	OIL CONSERVATION DIVISION
Title: FSA	Entered into RBDMS
E-mail Address: DQKB@Chevron.com	Re-test
Date: 7-16-15	
Phone: 575-704-2365	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

SEP 01 2015