

AUG 07 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT


Operator Name Chevron				API Number 3002502955			
Property Name Central Vacuum Unit				Well No. 65			
7. Surface Location							
UL - Lot E	Section 31	Township 17S	Range 36E	Feet from 1987	N/S Line N	Feet From 420	E/W Line W
							County Lea
Well Status							
YES	TA'D WELL NO	YES	SHUT-IN NO	INJ	INJECTOR SWD	OIL	PRODUCER GAS
							DATE 7/16/15

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	0		400	900
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO ₂ ✓
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ✓
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Production casing had 400lbs of gas & Packer Fluid bleed down to 0 in 30s.

Signature: 		BB 8/30/2015	
Printed name: Daniel Pace		OIL CONSERVATION DIVISION	
Title: FSA		Entered into RBDMS	
E-mail Address: DQKB@chevron.com		Re-test	
Date: 7-16-15	Phone: 575-704-2365		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM

SEP 01 2015