HOBBS OCD

AUG 31 2015

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name	API Number
Chevron	30-025-24312

Property Name	Well No.
Vacuum Grayburg San Andres Unit	34

Surface Location

UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County
J	1	18S	34E		2630	S	2630	E	LEA

Well Status

TA'D WELL	SHUT-IN	INJECTOR	PRODUCER	DATE
YES (NO)	YES (NO)	(INJ) SWD	OIL GAS	7-31-15

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	0	N/A	N/A	0	1735 (OK)
Flow Characteristics					CO2 X
Puff	Y / (N)	Y / N	Y / N	Y / (N)	WTR X
Steady Flow	Y / (N)	Y / N	Y / N	Y / N	GAS ___
Surges	Y / (N)	Y / N	Y / N	Y / (N)	Type of Fluid Injected for Waterflood if applies
Down to nothing	(Y) / N	Y / N	Y / N	(Y) / N	
Gas or Oil	Y / (N)	Y / N	Y / N	Y / (N)	
Water	Y / (N)	Y / N	Y / N	Y / (N)	

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 8/29/2015

Signature:	OIL CONSERVATION DIVISION
Printed name: Turner Dettman	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: TZYR@chevron.com	
Date: 7-31-15 Phone: 575 390 4449	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

SEP 01 2015