

HOBBS OCD

AUG 21 2015

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron						API Number 30-025-24361			
Property Name Vacuum Cracking San Andres Unit						Well No. 35			
Surface Location									
CL Lot 6	Section 1	Township 18S	Range 34E		Feet from 2630	NS Line N	Feet from 1330	W Line E	County LEA
Well Status									
YES	PAID WELL ☒	YES	SHEATH ☒	INJ ☒	SWD	OIL	PRODUCER	GAS	DATE 7-31-15

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	0	N/A	N/A	300	1750 OK
Flow Characteristics					
Pull	Y / ☒	Y / N	Y / N	Y / ☒	CO2 X
Steady Flow	Y / ☒	Y / N	Y / N	Y / N	WTR X
Surges	Y / ☒	Y / N	Y / N	Y / ☒	GAS —
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / ☒	Y / N	Y / N	Y / ☒	Injected for
Water	Y / ☒	Y / N	Y / N	Y / N	Water level if it applies

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

D- Bleed to zero pressure

BS 8/29/2015

Signature: Tanner DeHaven	OIL CONSERVATION DIVISION
Printed name: Tanner DeHaven	Entered into RBDMS
Title: PSA	Re-test
Email Address: TDXK@chevron.com	
Date: 7-31-15	Phone: 575-390-4449
Where:	

INSTRUCTIONS ON BACK OF THIS FORM

SEP 01 2015