

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name	Chevron	API Number	30-025-31875
Property Name	Vacuum Gloria West W	Well No.	108

Surface Location

BL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
P	36	17S	34E	213	S	351	E	LCA

Well Status

TA'D WELL	YES	NO	SHUT-IN	YES	NO	INJECTOR	YES	NO	PRODUCER	OIL	GAS	DATE
												7/21/15

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	Ø	N/A	N/A	Ø	1350
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Ø/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR X
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Ø/N	Y/N	Y/N	Ø/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

B2 8/30/2015

Signature:	Edgar Gallegos	OIL CONSERVATION DIVISION
Printed name:	EDGAR GALLEGOS	Entered into RBDMS
Title:	SSPS	Re-test
E-mail Address:	edgar@chevron.com	
Date:	7/21/15	
Phone:	575-631-8516	
Witness:	John Bone	

INSTRUCTIONS ON BACK OF THIS FORM

SEP 01 2015