

HOBBS OCD

AUG 07 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON USA INC		API Number 30-025-33623
Property Name Chambers Strawn Unit		Well No. 1

Surface Location									
U/L Lot H	Section 7	Township 16S	Range 36E	Feet from 1700	N/S Line North	Feet from 990	E/W Line East	County LEA	

Well Status									
TA'D WELL YES	NO	YES	SHUT-IN NO	INJECTOR INJ	SWD	OIL	PRODUCER GAS	DATE 6-24-15	

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0			0	0
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	Y / N	CO2 —
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ✓
Surges	Y / N	Y / N	Y / N	Y / N	GAS —
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterlevel if
					applies

Remarks — Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Jesse Covarrubia		OIL CONSERVATION DIVISION	
Printed name: Jesse Covarrubia		Entered into RBDMS	
Title: Field Specialist		Re-test	
E-mail Address: LKUO@chevron.com			
Date: 6-24-15	Phone: 575-704-2180		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM

SEP 01 2015