

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 20 2015

BRADENHEAD TEST REPORT

RECEIVED

LINE #27
N 1/2 NE 100 #1 STATE

300 253 8432 0000
6

7. Surface Location

UL Lot Section Township Range Feet from N/S Line Feet From E/W Line County
8 22S 37E LEA


Well Status

TA'D WELL YES NO YES SHUT-IN 0 INJ INJECTOR SWD (OIL) PRODUCER AS DATE 8-11-15

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	10			40	115
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:		88 8/29/2015
Printed name:	RUSSELL HESTON	OIL CONSERVATION DIVISION
Title:	FORMAN	Entered into RBDMS
E-mail Address:		Re-test
Date:	Phone:	
	Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

SEP 01 2015