State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

RECEIVED

Operator Name	API Number
Vanguard	30 - 025 - 37827

Property Name	Well No.
Cole St.	18

7. Surface Location

UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County
A	16	22S	37 E		330	N	990	E	Lea

Well Status

TA'D WELL		SHUT-IN		INJECTOR		PRODUCER		DATE
YES	NO	YES	NO	INJ SWD		OIL GAS		8/10/15

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	Ø	N/A	N/A	50	80
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 __
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR __ GAS __
Surges	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Down to nothing	Y / N	Y / N	Y / N	Y / N	Injected for
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Waterflood if
Water	Y / N	Y / N	Y / N	Y / N	applies.

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 8/29/ 2015

Signature:	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date: 8/10/15	Phone:
	Witness:

INSTRUCTIONS ON BACK OF THIS FORM