CDC caon

SEP 1 1 2015

District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Revised August 1, 2011 RECSubfinitione copy to appropriate District Office

NFO Permit No.

(For Division Use Only)

Form C-129

APPLICATION FOR EXCEPTION TO NO-FLARE RULE 19.15.18.12

(See Rule 19.15.18.12 NMAC and Rule 19.15.7.37 NMAC)

А.	Applicant <u>Murchison Oil & Gas, Inc.</u> , whose address is <u>7250 Dallas Parkway, Ste. 1400, Plano, TX 75024</u> ,	
	hereby requests an exception to Rule 19.15.1	8.12 for days or until,
	, Yr, for the following described tank battery (or LACT): Name of Lease Jackson Unit 20H (30-025-41139) Name of Pool Triple X; Bone Spring, West	
	Location of Battery: Unit LetterOS	ection <u>21</u> Township <u>24S</u> Range <u>33E</u>
	Number of wells producing into battery	2
B. Based upon oil production of <u>90</u> barrels per day, the estimated * w		barrels per day, the estimated * volume
	of gas to be flared is <u>110</u> MC	F; Valueper day.
C.	Name and location of nearest gas gathering facility:	
	Frac Cat Compressor Station, Lea County, N	<u>M</u>
D.	DistanceEstimated cost of connection	
E.	This exception is requested for the following reasons: <u>Intermittent curtailment by Agave due to</u> compressor maintenance. Well shut in at this time may damage formation and reduce future production	
OPERATOR		OIL CONSERVATION DIVISION
I hereby certify that the rules and regulations of the Oil Conservation Division have been complied with and that the information given above is true and complete to the best of my knowledge and belief.		Approved Until $12/9/2015$
Signature		By Majurs Brown
Printed Name		
	ry Cooper, Vice President Operations	
Email Addres	s rcooper@idmii.com	Date 9/14/2015

Telephone No. 972-931-0700 Date 9/9/15

Email Address rcooper@jdmii.com

* Gas-Oil ratio test may be required to verify estimated gas volume. 17