

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 14 2015

RECEIVED

BRADENHEAD TEST REPORT

Operator Name <u>Apache Oil Corp.</u>	API Number <u>06519</u>
Property Name <u>NEDU</u>	Well No. <u>207</u>

Surface Location

UL Lot <u>14</u>	Section <u>3</u>	Township <u>21S</u>	Range <u>37E</u>	Feet from <u>2970</u>	N/S Line <u>S</u>	Feet From <u>2308</u>	E/W Line <u>W</u>	County <u>Lea</u>
---------------------	---------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☒ NO ☐	SHUT-IN YES ☐ NO ☒	INJECTOR ☒ SWD	PRODUCER OIL ☒ GAS	DATE <u>3-26-19</u>
--	--	--	--	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	<u>1125 to 0</u>	<u>N/A</u>	<u>N/A</u>	<u>1140 to 0</u>	<u>1150</u>
Flow Characteristics					
Pull	☒ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N	☐ Y ☒ N	CO2 ☐
Steady Flow	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☐ N	☒ Y ☐ N	WTR ☐
Surges	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☐ N	☐ Y ☒ N	GAS ☐
Down to nothing	☒ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N	☒ Y ☐ N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	☒ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N	☒ Y ☐ N	
Water	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☐ N	☐ Y ☒ N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Surface - Gas only Blow Down 41 min.

Didn't do MIT because
Failed Bradenhead Test

Prod Casing - Gas only Blow Down 52 min.

Communicated with Tubing + casing

Failed
BS 7/28/2015

Failed Test

Pressured up and equilized with Tubing.

Signature: <u>Tracy Cole</u>	OIL CONSERVATION DIVISION
Printed name: <u>Tracy Cole</u>	Entered into RBDMS
Title: <u>Pumper</u>	Re-test
E-mail Address: <u>tracy.cole@apachecorp.com</u>	
Date: <u>3-26-15</u>	Phone: <u>575-441-5196</u>
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

SEP 18 2015