

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 28 2015

RECEIVED

BRADENHEAD TEST REPORT

Operator Name BREITBURN OPERATING		API Number 30-025-38917	
Property Name CONE JALMAT YATES POOL UNIT		Well No. 128	

7. Surface Location

UL - Lot 1	Section 13	Township 22 S	Range 35 E	Feet from 1910	N/S Line FSL	Feet From 725	E/W Line FEL	County LEA
----------------------	----------------------	-------------------------	----------------------	--------------------------	------------------------	-------------------------	------------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	XXX INJECTOR INJ	SWD	PRODUCER OIL	GAS	DATE 8-19-2015
------------------	----	----------------	----	---------------------	-----	-----------------	-----	--------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			0	980
Flow Characteristics					
Puff	Y / ☒	Y / N	Y / N	Y / ☒	CO2 ☐ WTR ☒ GAS ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies.
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Cam Robbins</i>		OIL CONSERVATION DIVISION	
Printed name: CAM ROBBINS		Entered into RBDMS	
Title: FORMAN		Re-test	
E-mail Address: cam.robbs@breitburn.com			
Date: 8-19-2015	Phone: 432-425-3001		
Witness:			

SEP 18 2015