

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 28 2015

BRADENHEAD TEST REPORT

RECEIVED

Operator Name BREITBURN OPERATING		API Number 30-025-08648	
Property Name CONE JALMAT YATES POOL UNIT		Well No. 107	

7. Surface Location

U/L - Lot D	Section 24	Township 22S	Range 35E	Feet from 660	N/S Line FNL	Feet From 660	E/W Line FWL	County LEA
-----------------------	----------------------	------------------------	---------------------	-------------------------	------------------------	-------------------------	------------------------	----------------------


Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	XXX INJ INJ	SWD SWD	OIL PRODUCER OIL	GAS GAS	DATE 8-19-2015
-------------------------	-----------	-----------------------	-----------	-----------------------	-------------------	----------------------------	-------------------	--------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csgng	(E)Tubing
Pressure	0	0		0	1020
Flow Characteristics					
Puff	☒ / N	Y / ☒	Y / N	☒ / N	CO2 ☐ WTR ☒ GAS ☐
Steady Flow	Y / ☒	Y / ☒	Y / N	Y / ☒	Type of Fluid Injected for Waterflood if applies.
Surges	Y / ☒	Y / ☒	Y / N	Y / ☒	
Down to nothing	☒ / N	Y / ☒	Y / N	☒ / N	
Gas or Oil	Y / ☒	Y / ☒	Y / N	Y / ☒	
Water	Y / ☒	Y / ☒	Y / N	Y / ☒	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 		OIL CONSERVATION DIVISION	
Printed name: CAM ROBBINS		Entered into RBDMS	
Title: FORMAN		Re-test	
E-mail Address: cam.robbs@breitburn.com			
Date: 8-19-2015	Phone: 432-425-3001		
Witness:			

BS 9/16/2015

SEP 21 2015