

AUG 28 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name BREITBURN OPERATING		API Number 30-025-08651	
Property Name CONE JALMAT YATES POOL UNIT		Well No. 602	

7. Surface Location

UL - Lot J	Section 24	Township 22S	Range 35 E	Feet from 1980	N/S Line FSL	Feet From 1980	E/W Line FEL	County LEA
---------------	---------------	-----------------	---------------	-------------------	-----------------	-------------------	-----------------	---------------

Well Status

T-A'D WELL YES NO		SHUT-IN YES NO		XXX INJECTOR INJ SWD	OIL PRODUCER GAS	DATE 8-19-2015
----------------------	--	-------------------	--	-------------------------	---------------------	-------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csnrg	(E)Tubing
Pressure	0	0		0	725
Flow Characteristics					
Puff	X / N	Y / X	Y / N	Y / N	CO2 ___ WTR X GAS ___
Steady Flow	Y / X	Y / N	Y / N	Y / X	Type of Fluid Injected for Waterflood if applies. —
Surges	Y / X	Y / N	Y / N	Y / X	
Down to nothing	X / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / X	Y / N	Y / N	Y / X	
Water	Y / X	Y / N	Y / N	Y / X	

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Cam Robbins</i>		OIL CONSERVATION DIVISION	
Printed name: CAM ROBBINS		Entered into RBDMS	
Title: FORMAN		Re-test	
E-mail Address: cam.robbins@breitburn.com			
Date: 8-19-2015	Phone: 432-425-3001		
Witness:			

SEP 18 2015