

AUG 28 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name BREITBURN OPERATING		API Number 30-025-38921	
Property Name JALMAT FIELD YATES SAND UNIT		Well No. 107	

2. Surface Location

UL - Lot B	Section 11	Township 22	Range 35		Feet from 627	N/S Line FNL	Feet From 2375	E/W Line FEL	County LEA
----------------------	----------------------	-----------------------	--------------------	--	-------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

TA'D WELL YES NO		SHUT-IN YES NO		XXX INJECTOR INJ	SWD	OIL PRODUCER GAS	DATE 8/19/2015
---------------------	--	-------------------	--	---------------------	-----	---------------------	-------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0		0	1090
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 <u> </u> WTR <u>X</u> GAS <u> </u> Type of Fluid Injected for Waterflood if applies
Steady Flow	Y / X	Y / X	Y / N	Y / N	
Surges	Y / X	Y / X	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / X	Y / X	Y / N	Y / N	
Water	Y / X	Y / X	Y / N	Y / N	

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Cam Robbins</i>		B8 9/23/2015 OIL CONSERVATION DIVISION	
Printed name: CAM ROBBINS		Entered into RBDMS	
Title: FORMAN		Re-test	
E-mail Address: cam.robbs@breitburn.com			
Date: 8/19/2015	Phone: 432-425-3001		
Witness: <i>[Signature]</i>			

SEP 24 2015