

HOBBS OGD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

SEP 09 2015

BRADENHEAD TEST REPORT

Operator Name Chevron USA Inc. Midcontinent, L.P.	API Number 30-025-10143
Property Name BRUNSON ARGO A	Well No. 11

7. Surface Location

UL - Lot A	Section 9	Township 23S	Range 37E	Feet from 731	N/S Line N	Feet From 589	E/W Line E	County LEA
---------------	--------------	-----------------	--------------	------------------	---------------	------------------	---------------	---------------

Well Status

Well Status	SHUT-IN	PRODUCING	DATE 8-31-15	INJ SWD
-------------	---------	-----------	-----------------	---------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	/	/		/	40
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:


CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ☒ WTR, ☐ GAS, ☐ CO2

shut in well

12-34
540

Signature: 	OIL CONSERVATION DIVISION
Printed name: Joseph Collins	Entered into RBDMS
Title: Production Specialist Sub-Surface	Re-test
E-mail Address: CollinsJ@chevron.com	
Date: 8-31-15	Phone: 575-631-4197
Witness:	

SEP 09 2015