

SEP 09 2015

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Lime Rock Resources II-A, L.P.	API Number 30-025-25066
Property Name North Vacuum ABO North Unit	Well No. #001

7. Surface Location

UL - Lot B	Section 2	Township 17S	Range 34E	Feet from 660	N/S Line North	Feet From 1780	E/W Line East	County Lea
---------------	--------------	-----------------	--------------	------------------	-------------------	-------------------	------------------	---------------

Well Status

Well Status - A	SHUT-IN	PRODUCING Injection	DATE 08-24-15
-----------------	---------	------------------------	------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	0	1800
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	


If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Tested by Eddie Elliott 432-413-0429

Reported by Trish Mealand 575-623-8424

Signature: 	OIL CONSERVATION DIVISION
Printed name: Trish Mealand	Entered into RBDMS
Title: Production Analyst	Re-test
E-mail Address: pmealand@limerockresources.com	
Date: 09-03-2015	Phone: 575-623-8424
Witness:	

SEP 25 2015