

SEP 08 2015

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name XTO Energy, Inc	API Number 30-025-28923
Property Name Seven Rivers Queen Waterflood, North	Well No. 10

7. Surface Location

UL - Lot F	Section 4	Township 22S	Range 36E	Feet from 2623	N/S Line North	Feet From 1330	E/W Line West	County Lea
---------------	--------------	-----------------	--------------	-------------------	-------------------	-------------------	------------------	---------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR <u>INJ</u>	SWD	PRODUCER OIL	GAS	DATE 3-25-2015
------------------	----	----------------	----	------------------------	-----	-----------------	-----	-------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csng	(E) Tubing
Pressure	Ø	Ø		Ø	448
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ___
Surges	Y / N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <u>Alan Miller</u>	OIL CONSERVATION DIVISION
Printed name: <u>ALAN MILLER</u>	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date: <u>3-25-2015</u>	Phone:
	Witness:

SEP 25 2015

gmb
FW