

SEP 09 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON USA INC.	API Number 30-025-29972
Property Name WEST TRAS YATES SEVEN RIVERS UNIT	Well No. 913

2. Surface Location

UL - Lot L	Section 09	Township 20S	Range 33E	Feet from 1980	N/S Line S	Feet From 660	E/W Line W	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR ☒ INJ	PRODUCER OIL ☒ GAS	DATE 7-16-15
--	--	--	--	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			32	40
Flow Characteristics					
Pull	Y / ☒ N	Y / N	Y / N	Y / ☒ N	CO2 ☐
Steady Flow	Y / ☒ N	Y / N	Y / N	Y / ☒ N	WTR ☒
Surges	Y / ☒ N	Y / N	Y / N	Y / ☒ N	GAS ☐
Down to nothing	Y / ☒ N	Y / N	Y / N	Y / ☒ N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y / ☒ N	Y / N	Y / N	Y / ☒ N	
Water	Y / ☒ N	Y / N	Y / N	Y / ☒ N	40 psi

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Joseph Collins	9/24/15 OIL CONSERVATION DIVISION
Printed name: Joseph Collins	Entered into RBDMS
Title: Production Specialist Sub Surface	Re-test
E-mail Address: CollinsJ@chevron.com	
Date:	Phone:
Witness: [Signature]	

INSTRUCTIONS ON BACK OF THIS FORM

SEP 25 2015