

SEP 09 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON USA INC.	*API Number 30-025 - 31896
Property Name WEST TEAS YATES SEVEN RIVERS UNIT	Well No. 921

7. Surface Location

UL - Lot C	Section 09	Township 20S	Range 33E	Feet from 330	N/S Line N	Feet From 2310	EAV Line W	County LEA
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☒	SHUT-IN YES ☒	INJECTOR ☒	PRODUCER OIL ☐ GAS ☐	DATE 7-16-15
---	---	--	---	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod C'sng	(E)Tubing
Pressure	0			45	0
Flow Characteristics					
Puff	Y / ☒	Y / N	Y / N	☒ / N	CO2 ☐
Steady Flow	Y / ☒	Y / N	Y / N	Y / ☒	WTR ☒
Surges	Y / ☒	Y / N	Y / N	Y / ☒	GAS ☐
Down to nothing	☒ / N	Y / N	Y / N	☒ / N	Type of fluid injected for Waterflood if applies
Gas or Oil	Y / ☒	Y / N	Y / N	Y / ☒	
Water	Y / ☒	Y / N	Y / N	Y / ☒	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Joseph Collins	OIL CONSERVATION DIVISION
Printed name: Joseph Collins	Entered into RBDMS
Title: Production Specialist Sub Surface	Re-test
E-mail Address: CollinsJ@chevron.com	
Date: 7-16-15	Witness:
Phone: 575-631-4197	

INSTRUCTIONS ON BACK OF THIS FORM

SEP 25 2015