Phone: (575) 393-6161 Fax: (575) 393-0720

HOBBS OCC

State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

RECEIVED

LRE Operating, LLC									30-025-35335		
Property Name Slippery Rock 20 State								Well No. #001			
					7. Surface Locat	tion					
UL - Lot J	Section 20	Township 17S	Range 35E		Feet from 2120	N/S L Sout		Feet From 1840	E/W Line East	County Lea	
					Well Status	S		•			
Well S	tatus – A	A	SHUT-IN		PRODUCING Oil		DATE 08-24-15				
f bradenheac			HEAD AND IN		OBSERVED DA		DUALLY F	OR 15 MINUTE	'S EACH	ب	
			urf-Interm		term(1)-Interm(2)	(C)Interm-Prod		(D)Prod 20	Csng	(E)Tubing	
Pressure		0		N/A	N/A		N/A			60	
Flow Charac	cteristics										
Puff	r		Y / <u>N</u>		Y / N		Y / N	7	Y / <u>N</u>	1	
Steady F			Y / <u>N</u>		Y / N		Y / N		<u>Y</u> / N		
Surge			Y / <u>N</u>	Y / N			Y/N		Y / <u>N</u>		
Down to no	~		Y/N		Y/N		Y/N		Y / <u>N</u>		
Gas or Wate			Y / N Y / N		Y / N Y / N	Y / N Y / N			<u>Y</u> / N Y / <u>N</u>		
CLEAR	1 HOWEL WA		check all of the descriptio		SALTY		SULFUR		BLACK		
Remarks:											
Tested by Edd Reported by T			i424								
Signature:	<u> </u>	11. M	COULLING					<u>B</u>	9/24/20	015	
(MIN		MUUL	<u>U</u>						N DIVISION	
Printed name								tered into RBD)MS		
Title: Produc							Re-	-test			
		nd@limerock	resources.com								
Date: 09-03-2	-2015		Phone: 575-	623-8424							
İ			Witness:								