

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

SEP 16 2015

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CHEVRON USA Inc	API Number 3002535985
Property Name TBAU	Well No. 26

2. Surface Location

1/4 - Lot B	Section 27	Township 12S	Range 38E	Feet from 330	N/S Line N	Feet from 2000	E/W Line E	County Lea
-----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	☒ NO	SHUT-IN YES	☒ NO	INJ ☒	SWD	OIL	PRODUCER	GAS	DATE 8/31/2015
------------------	-------------------------------------	----------------	-------------------------------------	---	-----	-----	----------	-----	--------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0		0	700
Flow Characteristics					
Puff	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	CO2 ☐
Steady Flow	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	WTR ☒
Surges	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	GAS ☐
Down to nothing	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	Type of Fluid
Gas or Oil	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	Injected or
Water	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Edythe Guller	B8 9/24/2015
Printed name: EDYTHE GULLER	OIL CONSERVATION DIVISION
Title: SSPS	Entered into RBDMS
E-mail Address: eiv9@chevron.com	Re-test
Date: 8/31/2015	
Phone: 575-441-4478	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

SEP 25 2015