

Failed SEP 09 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron USA Inc.	*API Number 30-025-36073
Property Name WEST TEAS YATAS SEVEN RIVERS Unit	Well No. WTE 924

7. Surface Location

UL - Lot F	Section 09	Township 20S	Range 33E	Feet from 2560	N/S Line N	Feet From 2210	E/W Line W	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJ	INJECTOR SWD	PRODUCER OIL	GAS	DATE 7-16-15
------------------	-----------	----------------	-----------	------------	-----------------	-----------------	-----	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			90 / Psi	0
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 —
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR X
Surges	Y / N	Y / N	Y / N	Y / N	GAS —
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Waterflood if applies
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

D - continuous flow

Failed

B8 9/24/15

Signature: Joseph Collins	OIL CONSERVATION DIVISION
Printed name: Joseph Collins	Entered into RBDMS
Title: Production Specialist sub surface	Re-test
E-mail Address: CollinsJ@chevron.com	
Date: 7-16-15	Phone: 575-631-4197
Witness: [Signature]	

INSTRUCTIONS ON BACK OF THIS FORM

SEP 25 2015