

SEP 21 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

RECEIVED

30-07-1-00048

Operator Name EGL Resources, Inc.		API Number 300 250048 0000
Property Name Moore Devonian Coop SWD System		Well No. 3

Surface Location

UL - Lot I	Section 14	Township 11S	Range 32 E	Feet from 1980	N/S Line FSL	Feet From 660	E/W Line FEL	County Lea
----------------------	----------------------	------------------------	----------------------	--------------------------	------------------------	-------------------------	------------------------	----------------------

Well Status

TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR ☒ SWD	PRODUCER OIL ☒ GAS	DATE 9-1-2015
--	--	--	--	-------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0				
Flow Characteristics					
Puff	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	CO2 ☐
Steady Flow	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	WTR ☒
Surges	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	GAS ☐
Down to nothing	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	Type of Fluid
Gas or Oil	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	Injected for
Water	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

B Bled off quickly GAS/AIR
D Took several seconds to bleed down - GAS/AIR
Bled off completely

Signature: David Lovelady		OIL CONSERVATION DIVISION	
Printed name: David Lovelady		Entered into RBDMS	
Title: Foreman		Re-test	
E-mail Address: david.2@eg1resources.com			
Date: 9-1-2015	Phone: 432-813-1084		
Witness: [Signature]			

SEP 28 2015