Submit 3 Copies To Appropriate District	State of New Mexico	Form C-103
Office <u>District I</u>	Energy, Minerals and Natural Resources	May 27, 2004 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II		30-025-23704
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE
District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		B-2244
	TCES AND REPORTS ON WELLS OSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPL	ICATION FOR PERMIT" (FORM C-101) FOR SUCH	NORTH VACUUM HOO NORTH UNIT
PROPOSALS.)	Gas Well X Other WATER INTECTION	8. Well Number 14#2
2. Name of Operator SAGE 2	Cas wen to one water macrior	9. OGRID Number
SHEE	NETBY COMPANY	020054
3. Address of Operator P.O. BOX 3068, // 4. Well Location	Midland TX 79702	10. Pool name or Wildcat NORTH VACUUM (Abo)
Unit Letter F: 1980 feet from the NORTH line and 1780 feet from the WEST line		
Section /Z	Township / 7-S Range 34-E	NMPM County LEA
	11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
Pit or Below-grade Tank Application	4026' GR	
Pit type Depth to Groundw	·· ·	
Pit Liner Thickness: mil		unce from nearest surface water ustruction Material 5 16
		(A)
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF IN		EQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	
TEMPORARILY ABANDON DULL OR ALTER CASING	CHANGE PLANS COMMENCE DRILL MULTIPLE COMPL CASING/CEMENT	
_	STORES CINETY	
OTHER:	OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
WELL FAILED I	MIT TEST 6/15/05. New tu	DING & DACKER WERE
WELL FAILED MIT TEST 6/15/05, NEW TUDING & PACKER WE'TE INSTALLED 8/27/05 AT WHICH TIME THE WELL PEMAINED SI DUE TO A SLIGHT WATERFLOW BETWEEN THE 6"CASING AND		
due to a succe matterior between the " casing man		
the 05/" are this area to the Court of the		
the 8%" csq. This Annulus was squeezer down the		
Fradenhead with 130 sacks of Class C NEAT CEMENT TO		
1700#. (10/18/05), This WELL PASSED ITS MIT TEST		
ON 11/9/05. (CHAPT ATTACHED)		
23/8" -169 AT		
23/8"x 6" LOKSET PACKER AT 8449-53" K.B.		
I hereby certify that the information a	bove is true and complete to the best of my knowledge a	nd belief. I further certify that any pit or below-
grade tank has been/will be constructed or c	osed according to NMOCD guidelines \square , a general permit \square or	an (attached) alternative OCD-approved plan 🗌.
SIGNATURE SUMMER SIGNATURE	wife TITLE DISTICT ENGINE	DATE ///21/05
TITLE DISTRICT ENGINEER DATE 1/21/05 Type or print name GEORE M. HARRIS TR. E-mail address: 9hArr (S. OSADEMIA) COMFelephone No. 683 5271		
APPROVED BY: Lange W.	OC FIELD REPRESENTATIVE II/STA	AFF MANAGER ADATE
		NUV 2 8 2005

