

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103

May 27, 2004

WELL API NO.	30-025-24182
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	OG-426 & E-26
7. Lease Name or Unit Agreement Name	Bagley State Com
8. Well Number	1
9. OGRID Number	227001
10. Pool name or Wildcat	Bagley; Permo Penn, North

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator  
Latigo Petroleum, Inc.

3. Address of Operator 550 W. Texas, Suite 700  
Midland, TX 79701

4. Well Location  
Unit Letter F : 1980 feet from the N line and 1980 feet from the W line  
Section 34 Township 11S Range 33E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
4286' GR

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type \_\_\_\_\_ Depth to Groundwater \_\_\_\_\_ Distance from nearest fresh water well \_\_\_\_\_ Distance from nearest surface water \_\_\_\_\_

Pit Liner Thickness: \_\_\_\_\_ mil Below-Grade Tank: Volume \_\_\_\_\_ bbls; Construction Material \_\_\_\_\_

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

11/14/05 - RU PU.

11/15/05 - Tried to unseat pump approx 1 1/2 hrs before rods parted. POOH & LD rods. ND WH & NU BOP. Worked tbg 3 hrs. Unable to release TAC or move tbg. Pulled 65,000# on 2 3/8" tbg. Left in tension overnight.

11/16/05 - RIH w/Baby Red overshot, 2' sub & 138 rods & latch up on rods body. Pulled to 25,000 & turned rods to the left 22 turns. POOH. Left overshot & 2' sub in hole. RIH w/rods & tried to screw back into 2' sub. 1st try pulled 4000 over & pulled off; 2nd try pulled 28,000 over & pulled off. Started out of hole.

11/17/05 - Finish POOH. Recovered 3/4" rod box. RIH w/overshot & latched up on 1 1/2" body of pin end on 3/4" rod. Pulled 5000# over & slipped off. Re-latch & pulled 15,000# over & slipped off. POOH. RIH w/3/4" short catch overshot. Caught threads on pin end. Pulled 25,000# over & slipped off. Could not latch again. POOH. Grapel pulled out of overshot and was still latched up on threads on pin end.

11/18/05 - RIH w/1 5/8" taper tap & tried to swallow grapple. POOH "dry run". RIH w/1 5/8" obannon overshot "dry run". RIH w/1 5/8" taper tap w/lip guide "dry run". RIH w/3/4" rod box looking down.

(Cont'd on back)

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOC guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Lisa Hunt

TITLE Regulatory Analyst

DATE 12/22/2005

Type or print name Lisa Hunt

E-mail address: lhunt@latigopetro.com

Telephone No. (432)684-4293

For State Use Only

APPROVED BY: Gay W. Wink

TITLE FIELD REPRESENTATIVE II/STAFF MANAGER

Conditions of Approval (if any)

DEC 28 2005

11/19/05 - Finish RIH & tried to screw rod box onto rod pin. Unable to get a bite. POOH. RIH w/7/8" rod pin & tried to wedge in top of 3/4" grapple. POOH "dry run".

11/21/05 - RIH w/1 3/4" impression block. POOH. Unable to determine what is looking up on rod pin. RIH w/7/8" rod box, spang jars, 3499' 7/8" rods & beat down on what I think is half of the 1 1/2" grapple that is latched onto the 3/4" rod pin. POOH. RIH w/new taper tap w/lip guide. Tried to swallow grapple or rod shoulder on rod pin. Worked rod string 1/2 hr & could not swallow or latch anything. POOH. Had bottom thread scratched on fishing tool.

11/22/05 - Calculate & determine tbg is stuck @ approx 7009'. RU Precision WL. RIH to make outside back off. 1st time went to 3535' & shot did not go off. POOH. Reload w/new string shot. RIH & set down @ 1500'. Worked line for 2 hrs. Unable to get past 1600'. POOH & re-head. RIH & made inside back off. Set down on top of fish @ 3442'. PU to 1st collar @ 3413' & back tbg off. POOH. RD WL.

11/23/05 - POOH w/111 jts 2 3/8" tbg (3411.74'). RIH w/Hillside sub & 111 jts & screwed back onto tbg (3411'). RIH w/Precision WL & made outside back-off @ 3504'. POOH & RD WL. POOH w/114 jts tbg (recovered 3 jts) (114 jts = 3500.08'). RIH w/oversocket & latched up on fish @ 3444'. Pulled 43,000# on fish & pulled loose. Could not re-latch. Tag top of fish 2' higher. POOH. Recovered 2' pony sub & top half of baby red overshot.

11/28/05 - RIH w/oversocket. Latched onto rods @ 3444'. PU 7 pts over string weight. Turned tbg to left. Turned 62 turns. Rods backed off. POOH w/fish. Recovered baby red, 15' rod piece, 8 - 3/4" rods & 3/4" box looking up. RIH w/tbg. Tried to screw back into tbg. Could not latch up. POOH w/tbg. PU tbg collar. RIH w/tbg. Screwed into fish.

11/29/05 - RIH w/shuck. Could not get on fish. POOH w/shuck. Nothing wrong. RIH w/shuck. Got on fish. PU 10# over string weight. Back off rods. POOH. Nothing in overshot. PU Bowen overshot. RIH w/overshot. Latched onto fish. Only got 3# over. Slipped off. Could not get back on.

11/30/05 - POOH w/overshot. Nothing in overshot. RU to pull tbg. Did blind back off. Back off tbg. Weight same. Tighten tbg. Did blind back off. POOH w/114 jts 2 3/8" tbg. Collar stripped out. Replace collar. RIH w/114 jts tbg. Tighten tbg. Did blind back off. Backed off approx @ 2500'. Screwed back onto tbg. RIH w/shuck. PU 3K#. Felt like it slipped off. Could not get back on rods. POOH. Had 31 - 3/4" rods in overshot.

12/1/05 - RIH w/shuck. Latched onto rods. POOH w/rods. Had 8 rds in overshot. RIH w/shuck. Latched onto fish. Jar on fish trying to release pump. Slipped off. POOH. Dry run. RIH w/1 1/2" Bowen overshot. Latched onto fish. Tried to PU. Rods parted. Gained 3K#.

12/2/05 - Check well press 0 psi. POOH w/overshot. 1/2 of grapple broke. RIH w/shuck. Slipped off. POOH. RIH w/new shuck. Latched onto fish. Pull off @ 25K. Shoulder of pin must be rounded off.

12/3/05 - Check well press 0 psi. POOH & LD rods. Total rods LD 144 - 7/8" (11 new) & 51 3/4" rods. Top of fish is 3/4" pin w/rounded off shoulder. Top of fish is approx 4600'. ND BOP. NU WH. Hang PR in well w/stuffing box.