


Deviation survey taken on EnerGen Resources  
in Lea County, New Mexico

30-025-37254


HODGE #2

K-27-125-38e

2240/5 & 2310/W



Depth	Deviation
419	0.50
892	0.50
1365	0.75
1702	0.75
2383	1.25
2891	0.50
3371	0.75
3846	0.75
4322	1.50
4581	1.00
5057	0.75
5532	1.00
6064	1.00
6506	1.00
6975	1.00
7726	0.25
8198	0.75
8856	1.25
9293	1.25
9814	1.50



Before me, the undersigned authority, on this day personally appeared G. M. HALL, known to me to be the person whose name is subscribed hereto, who, after being duly sworn, on oath states that he is the drilling contractor of the well identified in this instrument and that such well was not intentionally deviated from the vertical whatsoever.

SWORN AND SUBSCRIBED TO before me t this the 25<sup>th</sup> day of January 2005

Bunda Bills

Ka