

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised June 10, 2003

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-23869
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name LANGLIE JAL UNIT
8. Well Number #71
9. OGRID Number 188483
10. Pool name or Wildcat LANGLIE MATTIX (SRQBG)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☐ Other ☐ Water Injection

2. Name of Operator
Phoenix Hydrocarbons Operating Corp

3. Address of Operator
P O Box 3638, Midland, Texas 79702

4. Well Location
Unit Letter D : 660 feet from the North line and 510 feet from the West line
Section 8 Township 25S Range 37E NMPM Lea County NM

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3179' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☒ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐


OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

7/1/03 MIRU, unset 4-1/2" AD-1 packer; TOH w/tbg & pkr; TIH w 4-1/2" Klein plug & tbg; TOH w/tbg & retrieving tool; TIH w 4-1/2" AD-1 pkr, test plug to 1000 psi; tested csg, 10 stands at a time, ok; pull pkr, plug & tbg; TIH w/redressed 4-1/2" AD-1 pkr & tbg; circ 45 bbls pkr fluid, set pkr; Called Buddy Hill w/NMOCD to witness MIT; Mr Hill could not make it to the location; pressure up to 500 psi for 35 min, dropped 10 psi, chart attached.

Requesting TA status.

This Approval of Temporary
Abandonment Expires 7-17-08



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Phyllis R. Gunter TITLE Agent DATE 7/9/03

Type or print name Phyllis R. Gunter E-mail address: phygun@aol.com Telephone No. 432-686-9869
(This space for State use) FIELD REPRESENTATIVE II/STAFF MANAGER

APPROVED BY Larry W. Wink TITLE DATE JUL 17 2003
Conditions of approval, if any

