

OCT 06 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Apache Corporation	API Number 30-025-32512
Property Name WARN State A/C 3	Well No. 10

Surface Location									
UT-Lat H	Section 33	Township 17S	Range 35 E	Section 2150	N/S Line ENL	Section 500	East Line FEL	County Lea	

Well Status									
YES	NO	YES	NO	YES	NO	YES	NO	YES	NO
PROD	INJ	SWD	PROD	GAS	DATE				
					8-11-15				

OBSERVED DATA

	(A) Surface	(B) Intermediate	(C) Intermediate	(D) Casing	(E) Tubing
Pressure	10 ps.	0 ps.		15 ps.	30 ps.
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2
Steady flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Typical flow
GAS or Oil	Y/N	Y/N	Y/N	Y/N	Intermittent
Water	Y/N	Y/N	Y/N	Y/N	Water level

Remarks - Please state for each string (A, B, C, D, E) pertinent information regarding bleed down or continuous build up, if applies.

Signature: Albert De la Cruz	OIL CONSERVATION DIVISION
Printed name: Albert De la Cruz	Entered into RBDMS
Title: Pumper	Re-test
E-mail Address: albert.de la cruz @ apache corp. com	
Date: 8/14/15	Phone: 575-441-7730
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

OCT 06 2015