

SEP 25 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron U.S.A	API Number 30-025-06877
Property Name CDU Central Drinkard unit	Well No. 117

7. Surface Location

UL - Lot I	Section 29	Township 21S	Range 37E	Feet from 1980	N/S Line S	Feet From 660	E/W Line E	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

Well Status	SHUT-IN	PRODUCING INS	DATE 8/28/15	INS
-------------	---------	-------------------------	------------------------	------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csgng	(E)Tubing
Pressure				0	
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK ✓
-------	-------	-------	--------	----------------

Remarks: **Casing Had alot of Water. Needs a Trucl**
to make sure its Good.
9-6-15 - wen blew down to Nothing. 0 Flow
Hold for retest
INJECTING AT THIS TIME **WTR**, **GAS**, **CO2**

Signature: Saul Aranda Saul Aranda	OIL CONSERVATION DIVISION
Printed name: Saul Aranda	Entered into RBDMS
Title: FS A	Re-test
E-mail Address: SAVW@chevron.com	
Date: 8-28-15	Phone:
	Witness:

OCT 08 2015