

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

SEP 09 2015

BRADENHEAD TEST REPORT

Operator Name CHEVRON USA INC.	API Number 30-025-22841
Property Name Quail Queen Unit	Well No. 012

Surface Location

UL - Lot G	Section 11	Township 19S	Range 34E	Feet from 1980	N/S Line N	Feet From 1980	E/W Line E	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	NO	YES	SHUT-IN NO	INJECTOR IN	SWD	OIL	PRODUCER GAS	DATE 7-16-15
------------------	----	-----	---------------	-----------------------	-----	-----	-----------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	28			40	0
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR X
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

BLM ST/NM-06 4886

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Joseph Collins	OIL CONSERVATION DIVISION
Printed name: Joseph Collins	Entered into RBDMS
Title: Production Specialist Sub Surface	Re-test
E-mail Address: CollinsJ@chevron.com	
Date: 7-16-15	Phone: 575-631-4197
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

OCT 08 2015

88