

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name CHEVRON USA INC.	*API Number 30-025-26707
Property Name Quail Queen Unit	Well No. 11

2. Surface Location

UL - Lot A	Section 11	Township 19S	Range 34E	Feet from 990	N/S Line N	Feet From 990	E/W Line E	County LEA
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

YES	TA'D WELL ☒ NO	☒ YES	SHUT-IN NO	☒ INJ	INJECTOR SWD	OIL PRODUCER	GAS	DATE 7-16-15
-----	--	--------------------------------------	---------------	--------------------------------------	-----------------	-----------------	-----	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	20			170	260
Flow Characteristics					
Pull	☒ Y ☒ N	Y / N	Y / N	☒ Y ☒ N	CO2 ☐
Steady Flow	☒ Y ☒ N	Y / N	Y / N	☒ Y ☒ N	WTR ☒
Surges	☒ Y ☒ N	Y / N	Y / N	☒ Y ☒ N	GAS ☐
Down to nothing	☒ Y ☒ N	Y / N	Y / N	☒ Y ☒ N	Type of fluid Injected for Waterflood if applies.
Gas or Oil	☒ Y ☒ N	Y / N	Y / N	☒ Y ☒ N	
Water	☒ Y ☒ N	Y / N	Y / N	☒ Y ☒ N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Joseph Collins</i>	OIL CONSERVATION DIVISION
Printed name: Joseph Collins	Entered into RBDMS
Title: Production Specialist Sub Surface	Re-test
E-mail Address: Collins J @ chevron. com	
Date: 7-16-15	Phone: 575-631-4197
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

OCT 08 2015

BS