

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD
SEP 09 2015

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Chevron USA Inc.	API Number 30-025-23031
Property Name Quail Queen Unit	Well No. 8

2. Surface Location

UL - Lot K	Section 11	Township 19S	Range 34E	Feet from 2080	N/S Line S	Feet From 1980	E/W Line W	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☐ NO ☒	SHUT-IN YES ☒ NO ☐	INJECTOR INJ ☒ SWD ☐	OIL PRODUCER OIL ☐ GAS ☐	DATE 7-16-15
--	--	--	---	------------------------

OBSERVED DATA

Recheck

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	-600 gmb	0
Flow Characteristics					
Puff	Y/N ☒	Y/N ☐	Y/N ☐	Y/N ☒	CO2 ☐
Steady Flow	Y/N ☒	Y/N ☐	Y/N ☐	Y/N ☐	WTR ☒
Surges	Y/N ☒	Y/N ☐	Y/N ☐	Y/N ☐	GAS ☐
Down to nothing	Y/N ☒	Y/N ☐	Y/N ☐	Y/N ☒	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y/N ☒	Y/N ☐	Y/N ☐	Y/N ☐	
Water	Y/N ☒	Y/N ☐	Y/N ☐	Y/N ☒	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Csg had Puff-Down to zero - immediately - gmb 10/5/15
OK - gmb.
Re-check

rb

Signature: 	BS 10/3/15 OIL CONSERVATION DIVISION
Printed name: Joseph Collins	Entered into RBDMS
Title: Production Specialist Sub Surface	Re-test
E-mail Address: Collins J@chevron.com	
Date: 7-16-15	Phone: 575-631-4197
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

OCT 13 2015

OK
gmb