

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD
SEP 09 2015

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron U.S.A.	API Number 30-025-06845
Property Name CDU Central Dinkard	Well No. 111

7. Surface Location

UL - Lot G	Section 28	Township 21S	Range 37E	Unit Unit B	Feet from 1874	N/S Line N	Feet From 1874	E/W Line E	County CSA
----------------------	----------------------	------------------------	---------------------	-----------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

Well Status	SHUT-IN	PRODUCING	DATE 8-28-15	INI
-------------	---------	-----------	------------------------	------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure				0	821
Flow Characteristics					
Puff	Y/N	Y/N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y/N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y/N	Y/N	Y / N	Y/N	
Gas or Oil	Y / N	Y / N	Y / N	Y/N	
Water	Y / N	Y / N	Y / N	Y/N	

Water & Oil

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: INJECTING AT THIS TIME ☒ WTR, ☐ GAS, ☐ CO2

Needs Truck. We always get a truck on this one and Bleeds off real Quick, just don't want to make a mess on Location.

Signature: Saul Aranda 	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title: FS A	Re-test
E-mail Address: SAVW@chevron.com	
Date: 8-28-15	Phone: 575 402 1305
Witness:	

138 10/9/15

138

OCT 13 2015