

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

SEP 09 2015

BRADENHEAD TEST REPORT

Operator Name Chevron USA	API Number 30025 06896
Property Name CDU Central Drinkard U	Well No. 107

7. Surface Location

UL - Lot G	Section 29	Township 21S	Range 37E	Feet from 1980	N/S Line N	Feet From 1980	E/W Line E	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

Well Status	SHUT-IN	PRODUCING ☒	DATE 8/28/15	INS
-------------	---------	--	------------------------	------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure				0	011
Flow Characteristics					
Puff	☒ Y / N	☒ Y / N	Y / N	☒ Y / N	OK
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	☒ Y / N	☒ Y / N	Y / N	☒ Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ☒ WTR, ☐ GAS, ☐ CO2

Signature: Saul Aranda	BS 10/9/15
Printed name: Saul Aranda	OIL CONSERVATION DIVISION
Title: FS A	Entered into RBDMS
E-mail Address: SAVW@chevron.com	Re-test
Date: 8-28-15	
Phone: 575-402-1305	
Witness:	

OC, 13 2015