

SEP 09 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron U.S.A.	API Number 30-025-06978
Property Name CDU Central Drinkard U.	Well No. 141

7. Surface Location

UL - Lot E	Section 33	Township T21	Range R37E	Feet from 1980	N/S Line N	Feet From 660	E/W Line W	County LEA
----------------------	----------------------	------------------------	----------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

Well Status	SHUT-IN	PRODUCING	DATE 8-28-15	IN
-------------	---------	-----------	------------------------	-----------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure				0	5
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	Good
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME **WTR**, **GAS**, **CO2**

Signature: Saul Aranda [Signature]	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title: FS A	Re-test
E-mail Address: SAVW@chevron.com	
Date: 8-28-15	Phone: 575 602 1305
Witness:	

OCT 13 2015