

SEP 09 2015

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron U.S.A.	API Number 30-025-25224
Property Name CDU Central Dinkard U.	Well No. 413

7. Surface Location

UL - Lot B	Section 29	Township 21S	Range 37E	Feet from 910	N/S Line N	Feet From 1857	E/W Line E	County LEA
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

Well Status	SHUT-IN	PRODUCING <input checked="" type="checkbox"/>	DATE 8/28/15	INS
-------------	---------	--	------------------------	------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:


	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure				0	1058
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	Good.
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ☒ WTR, ☐ GAS, ☐ CO2

Signature: Saul Aranda 	OIL CONSERVATION DIVISION
Printed name: Saul Aranda	Entered into RBDMS
Title: FS A	Re-test
E-mail Address: SAVW@chevron.com	
Date: 8-28-15	Phone: 575-4602-1305
	Witness:

OCT 1 8 2015