HOBBS OCD

SEP 0 9 2015

State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

RECEIVED

			the second se	DENHEAD TES	ST REPORT	Г		
-			Operator Name	on U.S.A	~	3	· API Numbe	3909
			Property	DU Cen	tral Dr	inkard	4	ell No.
				7. Surface Location	on			
UL - Lot	Section 29	Township 215	Range 37 E	Feet from	N/S Line	Feet From 340	E/W Line	County
				Well Status				
Well	Status		SHUT-IN	PRODUCING	8	DATE -28-15	In	15 -

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csng	(E)Tubing
Pressure				0	1235
Flow Characteristics	-				
Puff	() N	TOR	Y/N	(V) N	OK
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y / N	Y/N	
Down to nothing	Ø/ N	Y/N	Y/N	O N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
Remarks:	No .	Interm	INJECTING AT THIS TIME	WTR,GAS,CO2

Printed name:		Entered into RBDMS	
Title: FS A		Re-test	
E-mail Address: SAVW@	chevron.com		
Date: 8-28-15	Phone: 675. 402: 1305		
	Witness:	N	